



Inspection Report

Bethyl Laboratories Inc.
P. O. Box 850
Montgomery, TX 77356

Customer ID: **1414**
Certificate: **74-R-0044**
Site: 001
BETHYL LABORATORIES, INC.

Type: ROUTINE INSPECTION
Date: Jan-22-2014

3.125 (a)

FACILITIES, GENERAL.

Multiple outdoor shelter facilities for the farm animals contain insulation material which is exposed in the ceiling of the structures. The plastic moisture barrier is damaged, torn and missing pieces leaving fiberglass insulation material exposed and dangling from the ceiling in some places.

The exposed fiberglass can be a conduit for moisture, contamination by organic material and mold growth. Additionally, falling fiberglass material can make contact with the skin or airways of the animals causing irritation. Some feeding is currently done in these shelters creating another opportunity for contamination by fiberglass.

Indoor and outdoor facilities must be kept in good repair to support the health of the animals and protect them from injury. The ceilings in the shelters should be repaired or replaced.

Correct by: July 24, 2014.

Exit interview conducted with management.

Prepared By:

Mary Moore DVM

MARY E MOORE, D V M USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER Inspector 1044

Date:
Jan-28-2014

Received By:

SENT VIA EMAIL

Title: PRESIDENT

Date:
Jan-28-2014